X00
14
CORNER
RECORDS,
PAGE_

 $\varpi$ 

City of	Document Number 20160036	
Brief Legal DescriptionLOT 14 BLOCK I, D	MAPS 17 AS SHOWN ON 19-RS-12, ORPC	
T.15N., R.16E. CORN M.D.B.& M. Government Corner Meander Rancho	IER TYPE COORDINATES (Optional)	
Corner− Left as found □ Found and tagged	☐ Established ☐ Reestablished ☑ Rebuilt ☐	
Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:		
● FD. 5/8" BAR WITH YELLOW PLASTIC CAP LS 7429 UNLESS OTHERWISE NOTED		
PER 19 ROS 12. USED BLOCK BREAKDOWN BY WEBB TO RECOVER PIPES		
ALONG HIGHWAY ROW. CALCULATED POSITION OF REMAINING 3 CORNERS OF LOT 14		
USING WEBB'S RESOLUTION AND RECOVERED PIPES AT BLOCK CORNERS ON HIGHWAY		
RIGHT OF WAY.	A.	
A description of the physical condition of the monument as found and as set or reset:  Q SET 5/8" REBAR WITH 2" ALUMINUM CAP STAMPED " TAHOE BASIN LAND		
SURVEYING THOMAS C. BUSWELL LS 5886	2 8 2 9	
SURVEYOR'S  This Corner Record was prepared by me or under my direction in consurveyor's Act on JULY 21 2016  Signed L.S. or R.C.E. Number	onformance with the Land  No. 5886  EXF. SEAL 31-12	
THOMAS C. BUSWELL  COUNTY SURVEYOR'S STATEMENT		
This Corner Record was Received20 and Exa		
signed The line Title County Suy	No. 6584 A Sp. 12-17	
County Surveyor's Comment	or cale	